

Ships Service



Onboard Ropes Inspection

Wilhelmsen Ships Service offers visual inspections of mooring ropes onboard your vessel – conducted by WSS specialists. You will receive an inspection report and recommendation for your mooring lines and mooring arrangements.



Why conduct a ropes inspection?

- Find any damages that can pose a hazard to onboard safety
- Prolong life of mooring lines by identifying areas that can be better handled
- Ensure best mooring solution for vessel/mooring design/
 ports
- Train crews in handling ropes the right way
- Inspection report for vetting inspector

With operations running 24/7 at ports globally, our port representatives can conduct an onboard inspection almost anywhere and anytime you'd like.

Based on the inspection, we will send you a confidential report with our findings and recommendations.

If you are interested, contact your WSS expert at: Phone: Email:



Surface abrasion on conventional ropes



Rope-on-rope abrasion and poorly maintained mooring system



Mixed mooring not recommended and poor mooring plan



Poorly maintained deck equipment



Broken rope cover



Broken rope cover



Pulled and cut fibers



Melted fibers

Wilhelmsen Ships Service Phone: (+47) 67 58 40 00 Fax: (+47) 67 58 40 80

Postal Address: PO Box 33, NO-1324 Lysaker, Norway

wilhelmsen.com



for a closer look